

### SAFE HOME / LEADSAFE CHARLOTTE

#### **CITY OF CHARLOTTE**

HOUSING & NEIGHBORHOOD SERVICES

### **BID OPENING CERTIFICATION RECORD**

Date of Bid Walk:5	131/18	Due Date:	6/7/18	NNS	
		Public Bod	y Estimate		
Address	PBE A	mount	PBE -15%		+15%
2329 Thornton	. 39,	165	33,2	90 4	5,040
	< 15%	ට/ද Bid Re	esults OK		
Addresses	Bidder 1 Bowman	Bidder 2	Bidder 3	Bidder 4	Bidder 5
2329 Thornton	29,200	and the second s			
	1, 100	8/15-10/1	5/12 7/10-8/3		
		60 days			
		Bid Walk /	\.	lak	
Yeshuas ?	ouldons	Signie	68	OIC DI	49-
Bownin C	mstr.	Red Re	oster con	tracter c	
JPGroup Ledbetter No	restv.				
This is to certify that bids fo Office located at 600 E. Trac Bids Opened By:	-	C	opened and read alou	, \	1
Witnessed By:		D	ate: JUNE 07	,2018€	Zpm
Note: Responsive bids are		nin a range of 15%	above and 15% below the property owner f	the public body co	



### SAFE HOME

**CITY OF CHARLOTTE** 

NEIGHBORHOOD & BUSINESS SERVICES

The Bids will be opened at 600 East Trade St. immediately following the above due date and time.

### **Company Acknowledgement:** The undersigned, having become thoroughly familiar with the terms, conditions, limitations, and provisions of the housing improvement work to be performed at 2329 Thornton Rd. to be funded through the City of Charlotte Neighborhood & Business Services, in addition, having fully inspected the site in all particulars, hereby proposes and agrees to fully perform the work within the time stated and in strict accordance with the proposed contract documents including furnishing of any and all labor and materials, and to do all work required to complete said Work in accordance with the advised respective contractual, for the sum of money: All labor, materials, services and equipment necessary for the completion of the Work shown on the Drawings and in the Specifications; True Thousand Live hundred Written total Number of Pages: 9 Specs Dated: 05/21/18 Addenda # 1 Dated: 06/01/18 Number of Pages: Addenda # 2 Dated: Number of Pages: **Contractor's Project Start Date:** ( Do not use TBD ) **Contractors Project Completion Date:** (Do not use TBD)

Please Print and Sign:
Company Name/Firm: \$5+443 Builders LLC
Authorized Representative Name:
Signature: Date: 6-7-18

G:\SELECTIVE REHAB TEAM\forms\bid forms and documents\Invitation to bid WARREN

Prepared By:
City of Charlotte Housing & Neighborhood Services
600 E. Trade Street
Charlotte, NC 28202
(704) 336-7600

Property Details	Addendum						
Address:	2329 Thornton Rd	C	Owner:	Franc	cedia Miller	•	
	Charlotte, NC 28208	C	Owner Phone:	Home	e: (704) 391	-2009	
Structure Type:	Single Unit	F	Program(s):		Safe		
Square Feet:	1174			Tested- NO LEAD Safe Home FY 2017			
Year Built:	1962				Home FY 2		
Property Value:	68800			Lead	Safe 2016		•
Tax Parcel:	0611308						
Census Tract:							
Property Zone:	Council District 3						
Repair Category: 00	.0 General Requirements						
<u>Description</u>				<u>Floor</u>	Room		<u>Exterior</u>
Dumpster					GENERA	L REQ	UIREMENER®erior
		any evider	nce of the dum				
	'	Bid Cost:	Base	_^	Quantity		Total Cost
Portable Toilet					•	L REQ	UIREMENER Gerior
	facilities from job start until approval of p	ermanent	facilities				27,401101
Trovido temporary temet	radinado irom job otari aria approvar or p	o manon			is a		
	1	Bid Cost:		_X	Malayan	_=	300
			Base		Quantity		Total Cost
Repair Category: 02	.0 Site Improvements						
<u>Description</u>				Floor	Room		<u>Exterior</u>
Exterminate Termites							
	Drill and patch foundation and pavemer optional yearly renewable warranty for the			rminato	or must be li	icensed	and provide a 1
	1	Bid Cost:	Name in Agreement Pall Control of the Control of th	_x	· · · · · · · · · · · · · · · · · · ·	=	1400
			Base		Quantity		Total Cost

<u>Description</u> Vinyl Soffit , Aluminum Fascia & Siding Repair  Install vented vinyl soffit to roof edges, ensuring existing soffit is			Eleor	Doom		Extor
• •			Floor	Room	20	<u>Exter</u>
the stall countries of the second and an according a confliction				EXTERIO		Exter
overhangs. Wrap all facia and wood trim with PVC coated alumin			ventilati	on, Install s	solia Vinyi	sonit to all ga
Repair / replace any decayed siding. Most decay occurs near bo approximately 36" from bottom of sheathing. Any decayed sheat						and
	Bid Cost:	Application of the contract of	х	- Silvery and a	= /,	1000-
		Base		Quantity		Total Cost
Prep & Paint Exterior Surfaces - EXTERIOR						
Prep and paint all exterior painted surfaces. Properly dispose all deteriorated materials. Caulk and fill all cracks, voids, holes, etc. color. All work to be done in a neat & professional manner. Use of	prior to appl	ying 25-yea	r or bett	er Low VO	C paint. C	Owners choice
	Bid Cost:	Company	Х	-discount of the state of the s	= /	500
	Dia 003t	Base		Quantity		Total Cost
Repair Category: 06.0 Roof, Chimney, Gutters & Down	nenoute	en e			igenja kristi ni s	and a far agreement
	lispouts	F 87	н.	-		a de la companya de l
<u>Description</u>			<u>Floor</u>	Room		Exter
				EXTERIO		Exter
Tear Off & Reroof Shingles		192 sq.ft. o	of deckir	ng replacen	nent in bid	d) and install
Tear Off & Reroof Shingles  Remove and dispose of existing roofing, inspect and repair roof of new 30 year architectural shingles. Include ice and water shield and all necessary accessories. (13.3)	deck (includલ at all roof ed(	ges, felt pap	er, shin	gle over rid	ge vent, i	oots, nasnin
Remove and dispose of existing roofing, inspect and repair roof onew 30 year architectural shingles. Include ice and water shield a	deck (include at all roof ede	ges, felt pap	er, shin	gle over rid	ge vent, i	ooos, nasning
Remove and dispose of existing roofing, inspect and repair roof onew 30 year architectural shingles. Include ice and water shield and all necessary accessories. (13.3)	at all roof edç	ges, felt pap	er, shin	gle over rid	ge vent, i	ooots, nasning
Remove and dispose of existing roofing, inspect and repair roof onew 30 year architectural shingles. Include ice and water shield and all necessary accessories. (13.3)	deck (include at all roof edo Bid Cost:	ges, felt pap	er, shin	gle over rid	_=	7300

6/1/2018

ixepair Category. Vo.o Doors & Williams				
Description		<u>Floor</u>	Room	<u>Exterior</u>
Vinyl Window				
Use Slider System Windows Dispose of window units and any security bars. Field measure, windows including half screens. Insulate rough opening. Install Exterior trim to be wrapped in PVC coated aluminum coll as ne installation is to include repairing any damaged header, framing joists and sill.	new extensior eded. Repair a	n jambs, casing an all areas disturbed	d sill as needed by removal and	, prime and paint. I installation. This
	Bid Cost:	X	=	3800-
	-	Base	Quantity	Total Cost
Sliding Glass Patio Door				
Remove and dispose of existing door, frame and threshold. Ins screen and locking hardware. Insulate cavity. New casing and any damaged header, door framing, wall framing, sub-floor, floor	shoe molding v	vill match existing.		
	Bid Cost:	X		1150-
			<del></del>	
		Base	Quantity	Total Cost
Repair Category: 10.0 Electrical		Base	Quantity	Total Cost
		Base Floor	Quantity  Room	Total Cost  Exterior
Repair Category: 10.0 Electrical		in in section of the		South the first grown and acceptance of the control
Repair Category: 10.0 Electrical  Description		Floor	Room KITCHEN	Exterior
Repair Category: 10.0 Electrical  Description  GFCI Receptacle 20 AMP  Install a flush mounted, ground fault circuit interrupted, duplex r	eceptacle and	Floor	Room KITCHEN	Exterior
Repair Category: 10.0 Electrical  Description  GFCI Receptacle 20 AMP  Install a flush mounted, ground fault circuit interrupted, duplex r		Floor cover plate. Chan	Room KITCHEN	Exterior
Repair Category: 10.0 Electrical  Description  GFCI Receptacle 20 AMP  Install a flush mounted, ground fault circuit interrupted, duplex r	eceptacle and	Floor cover plate. Chan	Room KITCHEN ge out other cor	Exterior  untertop outlet with  550  Total Cost
Description GFCI Receptacle 20 AMP Install a flush mounted, ground fault circuit interrupted, duplex r GFCI Fish wire and repair all tear out as needed.	eceptacle and Bid Cost:	Floor cover plate. Chan X Base	Room KITCHEN ge out other cou	Exterior  untertop outlet with  550  Total Cost  1 - MAIN
Description  GFCI Receptacle 20 AMP  Install a flush mounted, ground fault circuit interrupted, duplex r  GFCI Fish wire and repair all tear out as needed.  GFCI Receptacle 20 AMP	eceptacle and Bid Cost:	Floor cover plate. Chan X Base	Room KITCHEN ge out other cou	Exterior  untertop outlet with  550  Total Cost  1 - MAIN
Description  GFCI Receptacle 20 AMP  Install a flush mounted, ground fault circuit interrupted, duplex r  GFCI Fish wire and repair all tear out as needed.  GFCI Receptacle 20 AMP	eceptacle and  Bid Cost:  eceptacle and	Floor cover plate. Chan  X  Base  cover plate, Fish	Room KITCHEN ge out other cou	Exterior  untertop outlet with  550  Total Cost  1 - MAIN

5800

		-> su					95521171
Repair Category: 11.0 Plumbing & Fixtures			: .				
Description			Floor	<u>Room</u>			<u>Exterior</u>
Double Bowl Sink Complete				KITCHE	1		
install a 18 gauge 33" x 22" x 9" double bowl, stainless steel, se rated at 2.0 GPM or less, with a 15 year drip- free warranty, P-on all supply & drain lines. No copper compression fittings.	elf rimming kl irap, supply l	tchen sink in ines, full port	cluding a ball typ	a single hai e shut-off v	ndle met alves & e	al body escutch	faucet, eon plates
	Bid Cost:	The Control of the Co	Y	/	= 4	551	) —
	Bid Cost.	Base		Quantity		Total	Cost
17" Height Commode Replace				BATHRO	OM - M	AIN	
Install a 17" height, 2 piece, close coupled, white, vitreous china include plastic or pressed wood white seat, supply pipe, shut-of				er usage pe	r flush of	f 1.6 gal	llons.
	Bid Cost:	Character and the second	X	/	<b>=</b> _	350	7
		Base		Quantity	,	Total	Cost
Bathtub 5' Steel Complete				BATHRO	OM - M	AIN	
Install a 5' white, enameled, formed steel, tub complete with lev tub/shower diverter with water saving shower head. Install white horizontal edging, include horizontal window sill.	er operated e tile to 5' he	pop up drain ight at three	and ove sides of	erflow, PVC tub. Use bu	waste, s ıll-nose	single le verticle	ver &
	Bid Cost:	Many or commenced and a second and a second	X		<b>-</b> 2	50	7
	Biu Ooat.	Base		Quantity	- <i>-</i>	Total	Cost

#### Water heater 40 Gallon Gas

Remove existing water heater and all obsolete or deteriorated flue piping and gas line and dispose of properly. Remove and replace any decayed subfloor, joists & plates. Paint interior water tank closet walls.

Install an insulated 40 gallon, glass lined, high recovery gas water heater with a 10 year warranty and an Energy Factor of .61 or greater.

Installation includes PRV valve and extension, drain pan with drain to the exterior, expansion tank, and new gas line and flue piping through the roof as necessary to meet the requirements of the Construction Specifications and all relevant NC Codes.

	Bid Cost:	X	=	2/000-
,		Base	Quantity	Total Cost
Repair Category: 12.0 Floor			n ing pulita gang na dagama da babah da bang T	
Description		<u>Floor</u>	Room	<u>Exterior</u>
Resilient Flooring			LIVING ROOM	Exterior
Foyer Only (42" x 50") Install 25 year warrantied resilient floor coveri quarter-round at all perimeters to complete in		ions. Include transi	itions and painted	or stained wood
	Bid Cost:	Managaran parameter and a second a second and a second and a second and a second and a second an	=	300-
	bid cost	Base	Quantity	Total Cost
Floor System Repair			KITCHEN	
Remove all fixtures not built in. Dispose of flo all deteriorated wall studs, plates, girder band			ter, 3/4" subfloor.	Include replacing
	Bid Cost:	<u> </u>	l <u>=</u>	2800-
		Base	Quantity	Total Cost
Resilient Flooring			KITCHEN	
Install 25 year warrantied resilient floor cover quarter-round at all perimeters to complete in		ions. Include trans	tions and painted	or stained wood
	Bid Cost:	X.		1200-
		Base	Quantity	Total Cost

6/1/2018 5 /

#### **Resilient Flooring**

#### LAUNDRY / UTILITY

Install 25 year warrantied resilient floor covering per manufacturer's specifications. Include transitions and painted or stained wood quarter-round at all perimeters to complete installation.



#### Floor System Repair

**BATHROOM - MAIN** 

Remove all fixtures not built in. Dispose of floor assembly. Install 2"x 10" joists hung 16" on center, 3/4" subfloor. Include replacing all deteriorated band joists and insulating floor to code.

Decay will extend to Utility closet and Hall wall and floor. Plates, studs, drywall, joist and girder repair expected.



#### **Resilient Flooring**

**BATHROOM - MAIN** 

Install 25 year warrantied resilient floor covering per manufacturer's specifications. Include transitions and painted or stained wood quarter-round at all perimeters to complete installation.

Bid Cost:

Quantity

Repair Category: 13.0 Interior Wall & Trim

**Description** 

<u>Floor</u>

**Exterior** 

Prep & Paint Room Semi Gloss

Room KITCHEN

Remove or cover hardware and accessories not to be painted. Scrape loose, peeling, cracked and blistered areas. Clean oil, grease, fungus, dirt, and dust from surfaces. Fill holes and cracks. Prime all new materials and spot prime existing with acrylic latex. Top coat with owner's choice of low VOC acrylic SEMI-GLOSS latex. Replace or uncover hardware, fixtures and accessories. Any moving of furniture required shall be included. (33.27)



Quantity

6/1/2018

#### Prep & Paint Room Semi Gloss

#### LAUNDRY / UTILITY

Remove or cover hardware and accessories not to be painted. Scrape loose, peeling, cracked and blistered areas. Clean oil, grease, fungus, dirt, and dust from surfaces. Fill holes and cracks. Prime all new materials and spot prime existing with acrylic latex. Top coat with owner's choice of low VOC acrylic SEMI-GLOSS latex. Replace or uncover hardware, fixtures and accessories. Any moving of furniture required shall be included. (33.27)

	250		200
	7,11	-	
- Telephone	/ 2000		200
10000000000000000000000000000000000000			100000
1000年2017年		1000	
			1000
V			
F-1-E	4		3 5
	3047-306-3		-
	-		
· 美国 任 摄	400		
	\$ 180 cm -		4
	77-13		20000
3000	- 12		<b>F</b>
	· . 🚐		
24	- SE		
	A ===		753
20 to 1			119
			253
- DESTRUCTION			
<b>建筑是还</b> :			

#### Prep & Paint Room Semi Gloss

Remove or cover hardware and accessories not to be painted. Repair any large cracks & drywall holes. Shoe mold replacement if necessary. Repair loose ceiling finish and match repair.

Scrape loose, peeling, cracked and blistered areas. Clean oil, grease, fungus, dirt, and dust from surfaces. Fill holes and cracks. Prime all new materials and spot prime existing with acrylic latex. Top coat with owner's choice of low VOC acrylic SEMI-GLOSS latex, Replace or uncover hardware, fixtures and accessories. Any moving of furniture required shall be included. (33.27)



#### **Drywall Entire Room**

**BATHROOM - MAIN** 

Remove all gypsum, paneling, lathe and plaster or miscellaneous wall coverings to expose framing. Add insulation as required by code. Glue, nail and screw new drywall. Apply tape and 3 coats of joint compound to achieve a professional finish. Wet sand ready for paint, (Also 26.0 - Plaster)



Quantity **Total Cost** 

#### Prep & Paint Room Semi Gloss

#### **BATHROOM - MAIN**

Remove or cover hardware and accessories not to be painted. Scrape loose, peeling, cracked and blistered areas. Clean oil, grease, fungus, dirt, and dust from surfaces. Fill holes and cracks. Prime all new materials and spot prime existing with acrylic latex. Top coat with owner's choice of low VOC acrylic SEMI-GLOSS latex. Replace or uncover hardware, fixtures and accessories. Any moving of furniture required shall be included. (33.27)

(a)	43.	W.		
3				
		2		
	3700		7	1.50
	146		100	- 3
	-57			
			2	30.00
			100	
		57.5		<b>300</b>
高度	14.7			-
1860 P	112		: 23	
	7.2.电池	77	经	350

Bid Cost:	Nanpaine and American Control of the	Κ=	350
	Base	Quantity	Total Cost

Repair Category: 14.0 Ceiling

**Description** 

Floor

Room

<u>Exterior</u>

Ceiling Repair

KITCHEN

Repair celling finish. Replace any large areas's of drywall required- match ceiling texture, paint all.

Patch drywall or plaster holes in ceiling greater than one inch. All others use an adhesive mesh and mud over mesh with the appropriate material. Wet sand and smooth.



Bid Cost: _		_x(	_=4	500	
	Base	Quantity		Total Cost	

Repair Category: 16.0 Cabinets, Accessories & Appliances

Work Specification - City of Charlotte Housing & Neighborhood Services

**Description** 

<u>Floor</u>

Room

<u>Exterior</u>

**Cabinets Base** 

KITCHEN

Replace base cabinets. Cabinets to be constructed of solid maple and plywood. No particle board allowed. See contractor's manual guidelines & specifications for full requirements.

Repair any Upper cabinets which are in need of correction



Bid Cost: _	)	<b>(</b> =_	1200 -
	Base	Quantity	Total Cost

6/1/2018

#### **Counter Tops Replace**

#### **KITCHEN**

Screw to base cabinet a square edged plastic laminate counter top. Provide end-caps and cutout for sink. Caulk counter top to adjoining walls with low VOC caulking to match wall color. Owner's choice of in-stock color and texture. (32,10)



Bid Cost: X = 800

Base Quantity Total Cost

#### Vanity/ Counter Top/ Sink/ Replace Complete

#### **BATHROOM - MAIN**

Install new vanity cabinet complete with counter top of laminate with vitreous china sink or marble-lite top with preformed sink. Include single handled metal faucet with drain and pop-up, P- trap, supply lines, full port ball type shut-off valves & escutcheon plates.



Bid Cost: X = 750

Base Quantity Total Cost

Certification

Contractor Name:

Signature:

Total Cost:

Date:



### SAFE HOME

**CITY OF CHARLOTTE** 

**NEIGHBORHOOD & BUSINESS SERVICES** 

### Invitation to Bid

NOTE: Contractors are not authorized to visit the property before or after the bid walk, without being accompanied by the City's Rehabilitation Specialist.

#### **Documents included in Package:**

- 1) Instruction to Bidders
- 2) Specs by Location/Trade (Scope of Work)
- 3) Subcontractor Certifications (if applicable)
- 4) Floor Plan / Site Drawing (if applicable)

#### Bid Walk & Bid Opening:

Project Address: 2329 Thornton Rd.	SAFE HOME CHARLOTTE
Call project manager for full address	
Bid Walk: <b>5/31/18 at 11:00 am</b>	·
Bid Opening: 6/7/18 at 2:00 pm	
Client Name: Kenneth & Francedia Miller	Contact Number:
Project Manager: Chuck Hitsman	Contact Number: 704-336 3495

#### **Bid Walk and Bidding Instructions:**

All bid walks are mandatory.

If you are going to be late the policy is the following: Contact me BEFORE the start time if you are going to be late. If you are going to be more than 10 minutes late, we will proceed without you and you will not be permitted to bid.

The day of a bid walk the best way to reach me is at <u>Charles Hitsman</u>(cell # 704-622 1685 or <u>Amanda Woods 704 336 4114).</u>

Bids must be received by the date, time and place specified. All others will be considered non responsive and disqualified.